

FAQ on PSD XP 5.1 and programming problems with Roco Z21 and MultiMaus

If you have difficulties programming the PIKO SmartDecoder XP 5.1 with a Roco Z21 and MultiMaus, please note the following.

Since there were problems with the ACK pulse of the programming track in earlier versions, the Roco Z21 command station should have at least firmware 1.41 and the MultiMaus firmware 1.05. If necessary, the devices must be updated.

Otherwise it is possible that the CVs are read but not written.

Furthermore, the following programming settings of the command station should be made via the Z21 Maintenance Tool from Roco:

